

HSPV 540 American Building Technology Fall 2014



Redline Portfolio


Chuhan Zheng



HSPV 540 American Building Technology Fall 2014

Final Portfolio


Chuhan Zheng



Assignment 1 Bearing Wall Structures The Philadelphia Row House


Drawings of Elevation, Section & Plan Scale: 1/4" = 1'-0"

Avril 50, 3406 Sansom St., Philadelphia


















Drawings of Elevation and Section Scale: 3/4" = 1'-0"

3615 Locust Walk., Philadelphia















Assignment 2 Bearing Wall System Brick Masonry Wall and Opening

Photographs

3615 Locust Walk., Philadelphia





Assignment 3 Bearing Wall Structures Random Course Ashlar Masonry

Drawings of Elevation and Section Scale: 1/2"=1'-0"

249 South 36th St., Philadelphia

















Assignment 3 Bearing Wall Structures Random Course Ashlar Masonry

Photographs


249 South 36th St., Philadelphia



Assignment 4 External Joinery Double-Hung Vertical Sliding Sash Window

Drawings of Plan Scale: 6"=1'-0"







Interior

Assignment 4 External Joinery Double-Hung Vertical Sliding Sash Window

Drawings of Section Scale: 1"=1'-0"





Exterior




Assignment 4 External Joinery Double-Hung Vertical Sliding Sash Window

Drawings of Section at Top Scale: 6"=1'-0"






Exterior




Assignment 4 External Joinery- Double-Hung Vertical Sliding Sash Window

Drawings of Section at Center Scale: 6"=1'-0"



Exterior

Drawings of Section at Bottom Scale: 6"=1'-0"












Assignment 4 External Joinery Double-Hung Vertical Sliding Sash Window

Photographs



A reinforced concrete column after removal of the formwork



A "column to beam" connection with formwork attached




A "column to slab" connection

Assignment 5

Reinforced Concrete and Reinforced Concrete Frame Construction

Photographs



Strip Foundation with continuity steel reinforcement bars projecting



A "pad" foundation for a reinforced concrete column with continuity steel projecting




Formwork for a reinforced concrete column


Assignment 5

Reinforced Concrete and Reinforced Concrete Frame Construction

Photographs



A reinforced concrete retaining wall after removal of the formwork (on the left hand side)



A "flat slab" construction

A bush hammered concrete wall frame (At Skirkanish Hall, 210 South 33rd St., Philadelphia)

Assignment 5

Reinforced Concrete and Reinforced Concrete Frame Construction

Photographs



Formwork for a reinforced retaining wall



A reinforced concrete shear wall after removal of formwork

Assignment 5

Reinforced Concrete and Reinforced Concrete Frame Construction

Photographs



Column and baseplate to concrete foundation junction, with fireproof spray-on compound on column



Secondary "floor support beams" to main girder junction



Main girder to column junction with fireproof spray-on compound



Secondary "floor support beams" to main girder junction, with fireproof spray-on compound

Assignment 6 Steel Frame Construction

Photographs



Steel floor decking to support beam junctions, from bottom of the deck



Steel edge angles welded on to top of edge beams to contain the concrete floor slab, from top of decking



Closer view to the steel floor decking and support beam junction with fireproofing applied



Concrete floor slab cast on to steel decking

Assignment 6 Steel Frame Construction

Photographs



Fireproofing of columns with spray-on compound



Steel floor decking with steel main girders and steel supporting beams



Fireproofing of columns with spray-on compound at the stairs



Steel main girders with riveted joint

Assignment 6 Steel Frame Construction

Photographs



General condition of a Large deep basement excavation (view to northeast direction)

Assignment 7 Site Investigation Deep Excavations

Large Excavation Photographs

Arch St. and 18th St., Philadelphia




General condition of a Large deep basement excavation (view to south direction)

Assignment 7 Site Investigation Deep Excavations

Large Excavation Photographs



Temporary support system - Shoring



Temporary support system - Raker Bracing



Temporary support system - H Piles



Temporary support system - Soil Nailing

Assignment 7

Site Investigation Deep Excavations

Large Excavation Photographs

Arch St. and 18th St., Philadelphia



General conditions of a Small excavation site


Assignment 7 Site Investigation Deep Excavations

Small Excavation Photographs


Chestnut St. and 40th St., Philadelphia



Temporary support system - Shoring (in the back)



Temporary support system - H Piles (At Walnut St. & 30th St., Philadelphia)



Temporary support system -Weak concrete retaining wall



Temporary support system shoring structure burrie

Assignment 7 Site Investigation Deep Excavations

Small Excavation Photographs

Chestnut St. and 40th St., Philadelphia



Overall view of large caisson foundation





Caisson Foundation




Caisson Foundation

Assignment 7 Site Investigation Deep Excavations

Caisson Foundation Photographs

Walnut St. and 30th St., Philadelphia



Reinforced concrete retaining wall to a deep basement

Assignment 7 Site Investigation Deep Excavations

Large Excavation Deep Basement Photographs