
FORGOTTEN BOTTOM CHUHAN ZHENG • DI FAN

BASE MAP










HIGHWAY
RAILROAD
MAIN STREET
SCEONDARY STREET

OBSERVATIONAL MAP










ACCESSIBILITY>> ALTITUDE DIFFERENCE

OBSERVATIONAL MAP





ACCESSIBILITY >> Fence & Narrow Alley






Large vacant land in the industrial site-become parking lots.



The side of Grays Ferry ave is covered with garbage and abandoned structures.

There is also vacant land in residential area. Some is renovated into small yard, others is abandoned and full of weeds.

NO ONE GO...?














Though side walks in a good condition of maintainance, only

7 people were observed using the side walk during hour two hours site visit.





PHOTO JOURNAL - CHUHAN ZHENG

Y SMELL & INACTIVE PARK

The WM site seems currently not been used but the garbage smell still remains even on he bridge. The park along the river seemed to be specifically designed, but due to the height differences on the bridge, no one was observed using the park.



AWKWARD FACADE & VACANT FACTORY

The facades of many buildings still had traces from the buildings next door that were torn down. They were not covered which made them awkward like scars. Big amount of factories seemed to be abandoned at this time.

NO ONE CARE...?



LARGE VACANT LAND AROUND

Schuylkill River

The vacant lands were sometimes used as parking lot but in most of the time being vacant with weeds and fences.



GARBAGE EVERYWHERE

Garbages could be seen everywhere on the streets that seeemed not been cleaned for a very long time. Giving people an unconformtable experience of walking.

...BUT STILL SWEET

BIKE LANE

There is an effort of creating a better biking firendly streets of the city, showing the incentives of foster green transportation.





WARM DECORATIONS

Many houses have sweet decorations on their deck, showing their friendness to their neighbors as well as random people pass by.





HOME FOR CATS

Neighbors from the neighborhoods build a cat shelfter and dog shelter for the homeless animals.

0.6 Miles 0.075 0.15 0.3 0.45

ELEVATION


topography

ELEV
















TOPOGRAPHY





- Recent investment and /or maintenance
- No visible physical deficiencies
- Historic detailing -unique

- Minor repairs needed-cosmetic
- No evidence of structural issues or settling

E. Fair


- **Major painting** required
- Cracked windows or stairs

E. Distressed

- Poor exterior condition - peeling paint, demaged windows and frames evidence of roof deterioration
- Sloping or cracking evident on front facade

F. Failing

- **Vacant Shell**heavily damaged roof and window exposed to weather
- Structural deterioration evident interior piping/ Infrastructure removed



SOCIO-ECONOMICAL DATA ANALYSIS

